



LOT IDENTIFIER: Jimenez_Home

TOTAL SCORES: 93.33

ADDRESS: 17092 Sarah St, Louisa, 22960

INSPECTION DATE: 08/11/2023

A quality inspection was performed at the lot referenced above. Contained in this report is a summary of all defects identified during our process. Our process Includes a full inspection of paint (marked with Blue tape) and drywall (marked with Green tape), as well as trim defects that will be noted within. Some review items may include photos to assist in locating the items needing to be corrected. For your convenience our team may have marked items with yellow tape to further assist you in locating and identifying items listed within this report.



Disclosures

- THE INFORMATION CONTAINED IN THIS REPORT IS CONFIDENTIAL AND PROPRIETARY TO TRUE HOME REVIEW LLC ("TRUE HOME"). THIS REPORT IS BEING SUBMITTED TO Bethel Builders, LLC ("CLIENT") SOLELY FOR ITS CONFIDENTIAL USE IN CONNECTION WITH ITS INTERNAL QUALITY ASSURANCE PROGRAM. THIS REPORT IS NOT FOR THE USE OF, AND CANNOT BE RELIED UPON BY, ANY OTHER PERSON OR BE USED OR RELIED UPON FOR ANY OTHER PURPOSE. THIS REPORT DOES NOT CONSTITUTE A HOME INSPECTION. THE REVIEW CONDUCTED AND SERVICES PROVIDED TO PRODUCE THIS REPORT DID NOT INCLUDE A HOME INSPECTION AND SHALL NOT BE CONTRUED AS A HOME INPSECTION. THIS REPORT IS BEING PROVIDED BY TRUE HOME SUBJECT TO THE TERMS OF THE MASTER AGREEMENT BY AND BETWEEN TRUE HOME AND CLIENT.

Details

Total Items	Installation	Cosmetic	Cleanliness	Operational	Tasks	Missing
25	1	0	0	0	0	0

Paint	Drywall	Cleanliness	Woodwork
6	7	8	10

Systems And Safety

Air Returns/Filters 1

Installation Quality defect : Loose Installation noted